

# Draft Induced & Centrifugal Blowers

<p><b>90 CFM STOCK NO. 9619</b></p> <ul style="list-style-type: none"> <li>• 1/30-115-60-3200 • AMPS 1.35</li> <li>• Sleeve Bearing • Replaces: JAIN107, 490950, 4246100</li> </ul> 	<p><b>90 CFM STOCK NO. 9620</b></p> <ul style="list-style-type: none"> <li>• 1/20-115-60-3200 • AMPS 1.73</li> <li>• Sleeve Bearing • Replaces: JAIN114, 422030, 4246101</li> </ul> 	<p><b>90 CFM STOCK NO. 9621</b></p> <ul style="list-style-type: none"> <li>• 1/30-115-60-3200 • AMPS 1.35</li> <li>• Sleeve Bearing • Replaces: JAIN117, 430580, 4311200</li> </ul> 	<p><b>90 CFM STOCK NO. 9622</b></p> <ul style="list-style-type: none"> <li>• 1/20-115-60-3200 • AMPS 1.73</li> <li>• Sleeve Bearing • Replaces: JAIN118, 430590, 4311201</li> </ul> 
<p><b>95 CFM STOCK NO. 944</b></p> <ul style="list-style-type: none"> <li>• 1/50-115-60-1-3000 • AMPS 1.2</li> <li>• Sleeve Bearing • Direct OEM Replacement</li> <li>• Replaces: UE JA1M129, Fasco A143, 7021-8428, 7021-8924, Trane X3804-0305-010</li> </ul> 	<p><b>95 CFM STOCK NO. 959</b></p> <ul style="list-style-type: none"> <li>• 1/30-115-60-1-3300 • AMPS 0.9</li> <li>• Sleeve Bearing • Special mounting holes</li> <li>• Lead and plug assembly included</li> <li>• Replaces: UE JA1P082, Consolidated 401570</li> </ul> 	<p><b>98 CFM STOCK NO. 9447</b></p> <ul style="list-style-type: none"> <li>• 1/30-208-230-60-1-3000 • AMPS 0.6</li> <li>• Ball Bearing • Replaces: Fasco A150, 7021-7833</li> </ul> 	<p><b>100 CFM STOCK NO. 577</b></p> <ul style="list-style-type: none"> <li>• 1/50-115-60-1-3000 • AMPS 1.0</li> <li>• Sleeve Bearing • Replaces: Rheem 21504-03-04, 21496-03-01, Goodman B185900</li> <li>• Fasco A079, 7021-6804, UE JA1M106, JA1M137</li> </ul> 
<p><b>100 CFM STOCK NO. 673</b></p> <ul style="list-style-type: none"> <li>• 1/50-115-60-1-3000 • AMPS 1.0</li> <li>• Sleeve Bearing • OEM Replacement For Rheem 51-21504-01 • Trane</li> </ul> 	<p><b>100 CFM STOCK NO. 961</b></p> <ul style="list-style-type: none"> <li>• 1/50-115-60-1-3300 • AMPS 0.9</li> <li>• Sleeve Bearing • Direct OEM Replacement • Lead and plug assembly included • Replaces: UE JA1P092, Evcon 2702-3201A</li> </ul> 	<p><b>100 CFM STOCK NO. 966</b></p> <ul style="list-style-type: none"> <li>• 1/50-115-60-1-3000 • AMPS 1.0</li> <li>• Sleeve Bearing • Direct OEM Replacement</li> <li>• Lead and plug assembly included</li> <li>• Replaces: UE JA1M161, Rheem 09-189 (Transition Flange Included)</li> </ul> 	<p><b>105 CFM STOCK NO. 960</b></p> <ul style="list-style-type: none"> <li>• 1/30-115-60-1-3300 • AMPS 1.41</li> <li>• Sleeve Bearing • Replaces: UE JA1P090, Consolidated 401450</li> </ul> 
<p><b>105 CFM STOCK NO. 967</b></p> <ul style="list-style-type: none"> <li>• 1/30-115-60-1-3000 • AMPS 1.71</li> <li>• Sleeve Bearing • Replaces: UE JA1M195, GSW, Fasco</li> </ul> 	<p><b>105 CFM STOCK NO. 9430</b></p> <ul style="list-style-type: none"> <li>• 1/30-208-230-60-1-3000 • AMPS 0.6</li> <li>• Ball Bearing • Replaces: UE JB1N075NS, Armstrong 42250-001</li> </ul> 	<p><b>105 CFM STOCK NO. 9480</b></p> <ul style="list-style-type: none"> <li>• 115-60-1-3300 • AMPS 0.6</li> <li>• Sleeve Bearing • Replaces: Fasco 50757-D500</li> </ul> 	<p><b>118 CFM STOCK NO. 998</b></p> <ul style="list-style-type: none"> <li>• 1/15-115-60-1-3000 • AMPS 1.8</li> <li>• Sleeve Bearing • Replaces: Fasco A118, 7021-6999, 7021-7042, Williamson, Johnstone X89-520</li> </ul> 
<p><b>120 CFM STOCK NO. 9445</b></p> <ul style="list-style-type: none"> <li>• 1/55-120-60-1-3100 • AMPS 0.8</li> <li>• Sleeve Bearing • Replaces: Fasco 50746-D500, Nordyne</li> </ul> 	<p><b>130 CFM STOCK NO. 9496</b></p> <ul style="list-style-type: none"> <li>• 1/10-208-230-60-1-3000 • AMPS 0.55</li> <li>• Ball Bearing • PSC Motor • Replaces: JF1E021, Lennox 28G6601</li> </ul> 	<p><b>135 CFM STOCK NO. 9468</b></p> <ul style="list-style-type: none"> <li>• 1/25-115-60/50-1-2600 • AMPS 1.3</li> <li>• Sleeve Bearing • Replaces: Fasco B24220</li> </ul> 	<p><b>140 CFM STOCK NO. 9492</b></p> <ul style="list-style-type: none"> <li>• 1/50-115-60/50-1-3000 • AMPS 1.0</li> <li>• Sleeve Bearing • Replaces: WWG 4C442, Fasco 50752-D500</li> </ul> 

**Note:**  
For mounting dimensions see pages 21-23, for CFM data see page 24